




30 DEGREE FORMING PUNCHES AND DIES

#43



16 Ga



Probably the most universal type of press brake dies are the Acute angle dies. Their many functions include: forming 30° bends, also air forming to create angles greater than 30°, and as a first operation set in hemming. We recommend these types of dies as a starter set.


#45

14 Ga




22 Ga

#50




20 Ga

#52




18 Ga

#54



16 Ga

#56





14 Ga

#58

#47

12 Ga





12 Ga

#60


#49

10 Ga



11 Ga

#62




10 Ga

#64

#51

3/16



3/16

#66